

Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Relocation and area Protection



Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Mirror Replacement in Bathroom



Ceiling Replacement in Bathroom + Paint work



Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Cabinet Replacement in Bathroom



Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Ceiling Replacement in Bedroom + Paint work



Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Ceiling Replacement in Bedroom and Bathroom + Paint work



Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Wall Paint Work



Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Replacement of Built-in Cabinet



Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

Replacement of Built-in Cabinet





Millennium Residence Condominium TB121  
Replacement of Built-in Cabinet and ceiling repair work

งานเปลี่ยนพื้นไม้ส่วนที่ชำรุดเสียหายจากน้ำรั่ว



Millennium Residence Condominium TB121  
งานซ่อมแซมแนวข้อต่อท่อ Riser รั่วซึม

สกัดผนังช่องชาร์ป ซ่อมแซมท่อ PVC รั่ว โดยการอุดซ่อมและพันด้วย ชุดซ่อมท่อ Hardex



Millennium Residence Condominium TB121  
งานซ่อมแซมแนวข้อต่อท่อ Riser รั่วซึม

ก่อนอิฐฉาบปิดช่องชาร์ป ทาสีผนัง

